



Please note that in case you have version 1.3 or older versions, you must install first [version 1.4](#) and only then version 1.7

Improvements / changes of version 1.7 DAS240

Main improvements:

- TCP commands added
- New WiFi driver added
- Compatibility with LabVIEW driver

Minor bugs correction

Improvements / changes of version 1.5 DAS240

Main improvements:

- Alarm status is added in the status bar.
- Improvement of standard deviation calculation
- Channel increment added in the math calculation window
- Math calculation between cursors has been added
- Improvement of Pt100 3 wires with long integration period
- Web Services added and the download of files when recording is authorized

Minor bugs correction

This firmware update is fully compatible with **DAS240**



If you want to be informed of software releases and new products introduction, please follow-us on Twitter : [@SEFRAM SAS](#)